Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur





SriramRadha, 209, Jakkuru, Bengaluru, Karnataka 560001, India
Bengaluru
Karnataka
India





668, Ashwath Nagar, Saraipalya, Manayata Tech Park, Krishnarajpura Nagavara, Bengaluru, Karnataka 560045, India
Bengaluru
Karnataka
India

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur




GPS Map Camera
Bengaluru, Karnataka, India
192, near Trithwa Ashram, Saraipalya, New Bharath Layout, Thanisandra, Bengaluru, Karnataka 560064, India
Lat 13.060609°
Long 77.628451°

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur

No 123, Jakkur Government School Road, K V Bhyre Gowda Circle, Jakkur, Jakkuru, Bengaluru, Karnataka 560064, India
Bengaluru
Karnataka
India
26°C

No 123, Jakkur Government School Road, K V Bhyre Gowda Circle, Jakkur, Jakkuru, Bengaluru, Karnataka 560064, India
Bengaluru
Karnataka
India
26°C

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur



Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner

Name of Work: Improvements and Maintenance of Footpath in Wrad N0-08 Jakkur

Assistant Engineer
Ward No.08

Assistant Executive Engineer
Byatarayanapura Sub-Division

Scanned by CamScanner



Scanned by CamScanner





ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-24

Scanned by CamScanner